



# DATA SHEET

## LuminOx O<sub>2</sub> Sensors Luminescence-based Optical Series



### FEATURES

- Luminescence-based optical technology, NOT electrochemical
- Contains no hazardous materials; RoHS & REACH compliant
- Connects directly to a microcontroller without any additional circuitry
- Factory calibrated
- High accuracy
- Maintenance free<sup>a</sup>



<b>Housing</b>  COMPACT	<b>Supply Voltage</b>  4.5 - 5.5 V VOLTAGE	<b>Operating Temp</b>  +10°C to +45°C TEMPERATURE	<b>Output Digital</b>  TTL	<b>Response Time</b>  < 30 secs
--	--	---	--	--

### BENEFITS

- Low cost
- Low power, long life due to non-depleting sensing principle
- Compact footprint

### TECHNICAL SPECIFICATIONS

Supply voltage (Vs)	5V <sub>DC</sub> (4.5V <sub>DC</sub> min. —5.5V <sub>DC</sub> max.)
Supply current (Is)	<7.5mA (streaming one sample per second), <20mA Peak
Output Type	3.3V TTL level UART (5V tolerant)
Temperature	
Operating:	+10°C to +45°C
Storage:	-30°C to +60°C
Humidity	0—99% Rh (non-condensing)
Barometric pressure range	
LOX-01	100—1400mbar
LOX-02	500—1200mbar

### OUTPUT VALUES<sup>b</sup>

Oxygen range (LOX-02)	0—25% O <sub>2</sub>
Oxygen pressure range	0—300mbar ppO <sub>2</sub>
Response time	T <sub>90</sub> < 30s (typical)
Accuracy	
ppO <sub>2</sub>	< 2% FS
Temperature	Indication only
Pressure (LOX-02)	±5mbar
O <sub>2</sub> (LOX-02)	Determined by ppO <sub>2</sub> & pressure accuracy
Resolution	
ppO <sub>2</sub>	0.1mbar
Temperature	0.1°C
Pressure (LOX-02)	1mbar
O <sub>2</sub> (LOX-02)	0.01%
Lifetime	> 2 years

Other sensor options available on request, email:  
[technical@sstsensing.com](mailto:technical@sstsensing.com)

**Need help? Ask the expert**  
**Tel: + 44 (0)1236 459 020**  
**and ask for “Technical”**





- a) The sensor housing can be cleaned using a damp cloth. Do NOT immerse the sensor in any cleaning media.  
b) At ambient conditions. All performance measurements are at STP unless otherwise stated. Following extreme temperature fluctuations, re-calibration may be required.




## OUTLINE DRAWING

All dimensions shown in mm. Tolerances =  $\pm 0.5\text{mm}$ .



## ELECTRICAL INTERFACE



Pin	Designation
1	Vs (+5V)
2	GND (0V)
3	3.3V UART* Sensor Transmit
4	3.3V UART* Sensor Receive

\* 5V tolerant.

**Connection:** Four gold-plated pins ( $0.64\text{mm}^2$ ) on a  $2.54\text{mm}$  grid for PCB mounting via sockets or hand soldering using no-clean flux.

**Note:** If hand soldering, recommended iron temperature is  $370^\circ\text{C}$  for  $< 3\text{s}$  per pin.

**Note:** Do NOT put the sensor through a PCB washing process.

**Note:** Always apply power to sensor pins 1 and 2 before attempting to communicate on pins 3 and 4.

The sensor should be treated as an electronic component and handled using the correct ESD handling precautions.



## SENSOR CONSTRUCTION

### CAUTION

Do not exceed maximum ratings and ensure sensor(s) are operated in accordance with their requirements. Carefully follow all wiring instructions. Incorrect wiring can cause permanent damage to the device. Do NOT use chemical cleaning agents.

**Failure to comply with these instructions may result in product damage.**

**These products must not be used in safety applications where product failure could cause injury or risk to life**

### INFORMATION

As customer applications are outside of SST Sensing Ltd.'s control, the information provided is given without legal responsibility. Customers should test under their own conditions to ensure that the equipment is suitable for their intended application.

**For technical assistance or advice, please email:**  
[technical@sstsensing.com](mailto:technical@sstsensing.com)

## ORDER INFORMATION



Generate your specific part number using the convention shown below. Use only the numbers that correspond to the sensor option you require — omit those you do not.

L O X - X X

Type
<b>01</b> Measures 0—300mbar ppO <sub>2</sub> and temperature ( $^\circ\text{C}$ )
<b>02</b> Measures 0—300mbar ppO <sub>2</sub> , 0—25% O <sub>2</sub> , temperature ( $^\circ\text{C}$ ) and 500—1200mbar barometric pressure